

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	222	(package same cavity) and (cooling same (liquid or coolant))	USPA T	2004/01/20 09:32			0
2	BRS	L2	85	(package same cavity) and (cooling same (liquid or coolant))	US-P GPUB ; EPO; JPO; DERW ENT; IBM- TDB	2004/01/20 09:39			0
3	BRS	L4	103	3 not 2	US-P GPUB ; EPO; JPO; DERW ENT; IBM- TDB	2004/01/20 09:39			0
4	BRS	L5	379	(package) and ((cooling same (direct) same (liquid or coolant))	USPA T	2004/01/20 09:47			0
5	BRS	L6	350	5 not 1	USPA T	2004/01/20 10:05			0
6	BRS	L7	2553	257/\$.cccls. and (cooling same liquid)	USPA T	2004/01/20 10:06			0
7	BRS	L8	2448	7 not 1	USPA T	2004/01/20 10:06			0
8	BRS	L9	2366	8 not 6	USPA T	2004/01/20 10:06			0
9	BRS	L10	0	9 and (litographic adj spring\$1)	USPA T	2004/01/20 10:07			0
10	BRS	L11	433	9 and (spring\$1)	USPA T	2004/01/20 10:07			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
11	BRS	L12	243	9 and (contact\$1 same spring\$1)	USPA T	2004/01/20 10:14			0
12	BRS	L13	2123	9 not 12	USPA T	2004/01/20 10:14			0
13	BRS	L14	236	13 and (direct same cooling)	USPA T	2004/01/20 10:21			0
14	IS&R	L15	25	(("6205799") or ("6182742") or ("6108201") or ("5943211") or ("5924198") or ("5907473") or ("5724824") or ("5718117") or ("5434606") or ("5278584") or ("5220804") or ("4794410") or ("4685308") or ("4683481") or ("4576012") or ("4559789") or ("4500895") or ("4490728") or ("4352392") or ("4290274") or ("4141224") or ("2875263") or ("2858355") or ("2849523") or ("2643282"))).PN.	USPA T	2004/01/20 10:31			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
15	IS&R L16	29	(("6205799") or ("6182742") or ("6108201") or ("5992159") or ("5943211") or ("5924198") or ("5907473") or ("5797274") or ("5724824") or ("5718117") or ("5434606") or ("5278584") or ("5247426") or ("5220804") or ("5212975") or ("4794410") or ("4685308") or ("4683481") or ("4576012") or ("4559789") or ("4500895") or ("4490728") or ("4352392") or ("4290274") or ("4141224") or ("2875263") or ("2858355") or ("2849523") or ("2643282")) .PN.	USPA T	2004/01/20 10:31			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
16	IS&R L17 30		(("6205799") or ("6096656") or ("6038129") or ("6007690") or ("6001231") or ("5987893") or ("5978216") or ("5976336") or ("5965410") or ("5957579") or ("5932940") or ("5907473") or ("5876187") or ("5842787") or ("5709337") or ("5670722") or ("5596228") or ("5465192") or ("5443890") or ("5390077") or ("5376252") or ("5309319") or ("5237484") or ("5170319") or ("5161089") or ("5105336") or ("4897762") or ("4729424") or ("3843910") or ("3774677")) .PN.	USPA T	2004/01/20 10:32			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
17	IS&R L18	15	((("5111277") or ("5034688") or ("5032897") or ("4950181") or ("4926242") or ("4805420") or ("4758926") or ("4730665") or ("4447842") or ("4285002") or ("4253515") or ("4010489") or ("3942010") or ("2881370") or ("2863994"))).PN.	USPA T	2004/01/20 10:37			0
18	IS&R L19	9	((("2266427") or ("5065279") or ("5053853") or ("5031025") or ("4748495") or ("4547834") or ("4186422") or ("3706010") or ("3365620"))).PN.	USPA T	2004/01/20 10:37			0
19	BRS L3	114	(package) and (cooling same direct) same (liquid or coolant))	US-P GPUB ; EPO; JPO; DERW ENT; IBM TDB	2004/01/20 10:46			0
20	BRS L20	0	contacts same (litographic adj springs)	USPA T	2004/01/20 11:28			0
21	BRS L21	0	(litographic adj springs)	USPA T	2004/01/20 10:47			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
22	BRS	L22	0	(lithographic adj springs)	USPA T	2004/01/20 10:47			0
23	BRS	L23	8	((compliant or resilient or elastic) adj contacts) and (liquid same cooling)	USPA T	2004/01/20 11:32			0
24	BRS	L24	2	((compliant or resilient or elastic) adj contacts) and (liquid same cooling)	US-P GPUB ; EPO; JPO; DERW ENT; IBM- TDB	2004/01/20 11:25			0
25	BRS	L25	0	(litographic adj springs)	USPA T	2004/01/20 11:28			0
26	BRS	L26	0	(lithographic adj springs)	USPA T	2004/01/20 11:28			0
27	BRS	L27	42	(lithographic same springs)	USPA T	2004/01/20 11:28			0
28	BRS	L28	9	((compliant or resilient or elastic or springs) adj contacts) and (liquid same cooling)	USPA T	2004/01/20 11:33			0
29	BRS	L29	128	((springs) same contacts) and (liquid same cooling)	USPA T	2004/01/20 11:38			0
30	BRS	L30	418	(active adj surface\$1) and (liquid same cooling)	USPA T	2004/01/20 11:49			0
31	BRS	L31	958	(semiconductor\$1 or die\$1) same (contacts or surface\$1) same (liquid same cooling)	USPA T	2004/01/20 11:51			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
32	BRS	L32	5	(semiconductor\$1 or die\$1) same ((contacts or surface\$1) same (liquid same (direct adj cooling)))	USPA T	2004/01/20 12:00			0
33	IS&R	L33	14	((("5388635") or ("5373417") or ("5345107") or ("5323292") or ("5291064") or ("5239200") or ("5237203") or ("5102829") or ("5049973") or ("4982267") or ("4825284") or ("4573067") or ("4392153") or ("3746947"))).PN.	USPA T	2004/01/20 12:02			0
34	IS&R	L34	10	((("5829128") or ("5759014") or ("5666190") or ("5452268") or ("5354712") or ("5342737") or ("5308443") or ("5032896") or ("4961052") or ("4312117"))).PN.	USPA T	2004/01/20 12:15			0
35	BRS	L35	6	(cooling same liquid) same (gap same between same chip same board)	USPA T	2004/01/20 12:39			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
36	BRS	L36	2	(cooling same liquid) same (gap same between same chip same board)	US-P GPUB ; EPO; JPO; DERW ENT; IBM_ TDB	2004/01/2 0 12:41			0
37	BRS	L37	0	(cooling same liquid) same (gap same between same (semiconductor or die or processor) same board)	US-P GPUB ; EPO; JPO; DERW ENT; IBM_ TDB	2004/01/2 0 12:41			0
38	BRS	L38	2	(cooling same liquid) same (gap same between same (semiconductor or die or processor) same board)	USPA T	2004/01/2 0 12:43			0
39	BRS	L39	11	(cooling same liquid) same (space same between same (semiconductor or chip or die or processor) same board)	USPA T	2004/01/2 0 12:43			0
40	BRS	L40	3	(cooling same liquid) same (channel same between same (semiconductor or chip or die or processor) same board)	USPA T	2004/01/2 0 12:44			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
41 BRS	L41	59	(cooling same liquid) same (between same (semiconductor or chip or die or processor) same board)	USPA T	2004/01/2 0 12:48			0
42 BRS	L42	39	(cooling same liquid) same (between same (semiconductor or chip or die or processor) same board)	US-P GPUB ; EPO; JPO; DERW ENT; IBM- TDB	2004/01/2 0 12:48			0